


SC4 Engineering Lathe

Floor Stand Instructions

Contents

A	Left Leg
B	Right Leg
C	Back Panel
D	Front Panel
E	Drip Tray




Assembly

1: Take front panel (D) and line up with holes in left leg (A). Fix into place with socket head bolts and nuts supplied, see figs 01-02-03-04.




01



02



03



04

2: Line up right leg (B) to front panel attached to left leg and fix in to place with socket head bolts and nuts supplied, see fig 05-06.



05



06

Continues over...

3: Repeat the same process for the back panel (C), see figs 07-08-09.



07




08



09

4: Screw in the lathe fixing studs into the six threaded holes into the top of each leg, see fig 10-11-12.



10



11



12

5: Place the drip tray over the six studs attached. You are now ready to mount the lathe, see fig 13-14.



13



14