

Hot Melt Adhesive / 798HA

2016/5/5 : Update

1. Chemical Product And Company Identification

Product Name	798HA		
Product Type	Hot Melt Adhesive		
Suggested purpose and limitations	Bonding, adhesion		
Company Name	TEX YEAR INDUSTRIES INC.		
Company address	No.9, Wuquan 6th Rd., New Taipei Industrial Park, New Taipei City 24889, Taiwan (R.O.C.)		
Company Tel & Fax	Tel: +886-2-2299-2121 Fax: +886-2-2290-1650		

2. Hazardous Identification

Hazardous Category	Non-hazardous substances	
GHS label	None	
Label Content		
Symbol	None	
Warnings	Do not touch it directly while melting by heat to avoid scalding	
Hazard warning message	Touching it directly while melting by heat will cause contact burns.	
Hazard prevention measures	None	
Other hazards	None	

3. Composition, Information On Ingredients

Mixture		
Ingredients	CAS No.	WT%
Ethylene Vinyl Acetate Copolymer	24937-78-8	40%
Petroleum Resin	64742-16-1	15%
Rosin Ester	8050-26-8	20%
Anti Oxidant	6683-19-8	1 %
Inoganic Filler		24%
Hazardous ingredients	None	

4. First Aid Measures

Ingestion	Seek medical attention immediately.	
Inhalation	If symptomatic, move to fresh air. Get medical attention if symptoms persist.	
Skin Contact	Immediately flush skin with large amounts of cold/ice water for at least 30 minutes. DO NOT ATTEMPT TO REMOVE MOLTEN MATERIAL. Cover affected area with a clean dressing. Seek immediate medical attention.	
Eye Contact	Immediately flush eye with large amounts of cold water for at least 30 minutes. DO NOT ATTEMPT TO REMOVE MOLTEN MATERIAL. Cover affected area with a clean dressing. Seek immediate medical attention.	
Most importan symptoms and hazardous effects Protection for first aid personnel	Redness, swelling, and pain caused by burns. Immediately flush the burned part with large amounts of cold/ice water for at least 30 minutes. DO NOT ATTEMPT TO REMOVE MOLTEN MATERIAL. Cover affected area with a clean dressing. Seek immediate medical attention.	
Recommendations to physicians	_	



Material Safety Data Sheet

Hot Melt Adhesive / 798HA

2016/5/5 : Update

5. Fire Fighting Measures

Extinguishing Agents	Water spray, dry chemicals.		
Special fire fighting hazards	None		
Special Firefighting Procedures	 Use water or dry chemical for fire extinguishing; small-scale of fire can use the way of sprinkling water. Sprinkle the source of ignition with water to lower its temperature. Sprinkling products in molten state at large-scale fire will cause the splashing of hot water and melting products. It's required to wear protective clothing with a supply of respiratory equipment. After the fire is extinguished, isolation zone should be set up before cooling and curing of the internal products. 		
Special protective equipment of firefighters	Wear self-contained breathing apparatus and protective clothing.		

6. Accidental Release Measures

Individual precautions	Avoid contacting the hot melting materials with skin and eyes from getting burns.	
	In accordance with international conventions or local regulations. Incineration at the government-approved incineration.	
Cleaning Method	Use broom and dustpan for cleaning	

7. Handling And Storage

6 6	
Handling	Avoid contacting the hot material with the skin. Avoid children from touching.
	Avoid contacting with oxides, exposuring under the sun, and be away from the fire. Stored in sealed containers (to prevent dust pollution)

8. Exposure Controls, Personal Protection

None		
ex (BEI)		
iot		
Heat insulation gloves		
safety goggle		
No specific requirement		



Hot Melt Adhesive / 798HA

2016/5/5 : Update

9. Physical And Chemical Properties

States of Matter	solid	Odor	resin
Olfactory threshold	No applicable	Melting point	No applicable
pH	No applicable	Boiling Point	No applicable
Flash point	over 392°F,200°C	Flammability (solid, liquid)	No applicable
Test method	■open cup □ closed cup	Decomposition temperature	—
Auto-ignition temperature	No applicable	Explosion limit	No applicable
Specific Gravity	1.10 ~ 1.30	Solubility	No applicable
Evaporation Rate	No applicable	octanol / water partition coefficient (log Kow)	No applicable
Shape	Granule	Color	light yellow
Soften Point	$88 \pm 5^{\circ}C$	Viscosity(200°C)	36,500~49,500cps

10. Stability And Reactivity

Stability	Stable
Special Conditions Of Hazardous Reaction	Not applicable
Conditions to Avoid	Temperature above 200°C
Incompatibility Hazardous Decomposition	might react with strong oxidant
Products	Flammable Hydrocarbon, carbon monoxide and fumes.

11. Toxicological Information

Exposure approach	None	
Symptoms	None	
	Inhalation	Inhalation of dust and smoke will stimulate the respiratory system.
	Skin	None
	Eye	None
Acute Toxicity	LD50(testing animal's absorption approach)	No data
	LC50(testing animal's absorption approach)	No data
	500mg/24hr(rabbit, skin)	No data
	20mg/24hr(rabbit, eyes)	No data
chronic toxicity or long-term toxicity	None	

12. Ecological Information

Ecological Toxicity	LC50(fish)	No data	
	EC50(aquatic invertebrates)	No data	
Sustainable and De-toxic	Difficult to naturally degrade, but can be recycled by appropriate ways		
Ecologic Accumulation	No data		
Liquidity in Soil	No data		
Other poor Effect	Improper burning may generate hazardous gas.		



Hot Melt Adhesive / 798HA

2016/5/5 : Update

13. Disposal Considerations

G2	1. Refer to relevant regulations
Disposal considerations	2. Storage waste according to storage conditions
	3. Able to apply specific incineration or sanitary land filling
14. Transportation Information	
The United Nations Number(UN_No)	None
The United Nations Shipping Name D.O.T. Hazard Class	None
	None
Package Category	None
Maritime Pollutants(yes/no)	No
International Transport Regulation	Not regulated
Domestic Transport Regulation	Not regulated
Special Transport Way And Note	Not regulated

15. Regulatory Information

1. Rules of labor safety and health facilities

2.Rules on Hazard Communication of Dangerous Materials and Toxic Materials

3.Organic solvent poisoning prevention regulation

4. Standards of Permissible Exposure Limits of Airborne Hazardous Substances in Workplace

5. Road Traffic Safety Regulation

6.Methods and Facilities Standards for the Storage, Clearance and Disposal of Industrial Waste

7. Public Hazardous Substances & Flammable Pressurized Gases Establishment Standards & Safety Control Regulation

16. Other Information

	Health Hazard	1
	Fire Hazard	1
	Reactivity Hazard	0
	Specific Hazard	None

Prepared Company	TEXYEAR INDUSTRIES INC.
Company Telephone	886-2-2299-2121
Prepared By	Dept. Researcher
Revision Date	2016/5/5